

Oil Field Environmental Incident Summary

Incident: 20160205180353

Date/Time of Notice: 02/05/2016 18:03

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: ND STATE 24-16H-0916-15895-TF

Field Name: MCGREGOR

Well File #: 23205

Date Incident: 2/5/2016

Time Incident: 11:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 16

Qtr:

Location Description:

Submitted By: Tappan Souther

Received By:

Contact Person: Tappan Souther
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

3 BBLS of produced oil.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

100% of spill contained in earthen berm surrounding tank battery.

Potential Environmental Impacts:

None.

Action Taken or Planned:

Rubber hose was removed and replaced with steel pipe.

Wastes Disposal Location: Local disposal.

Agencies Involved:

Updates

Date: 2/10/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.